10/609,492

## **EAST Search History**

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp ·
L14	0	(error rate controller AND data signal AND control signal AND control signal error rate AND power variable unit AND W-CDMA system).clm.	US-PGPUB; USPAT; USOCR	ADJ	ON	2006/10/12 19:48

## **EAST Search History**

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L1	561271	receiv\$3 and ("TFCI" or control signal\$1 or PILOT or TPC)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	ADJ	ON	2006/10/12 19:15
L2	833	detect\$3 and ("TFCI error\$1" or control signal error\$1)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	ADJ	ON	2006/10/12 19:16
L3	667	(comput\$4 or calculat\$3 or count\$3) and ("TFCI error\$1" or control signal error\$1)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	ADJ	ON	2006/10/12 19:18
L5	1	compar\$3 and (("TFCI error rate" or control signal error rate) and ("TrCH error rate" or expected error rate))	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	ADJ	ON .	2006/10/12 19:20
L6	671	I1 and I2	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	ADJ	ON	2006/10/12 19:20
L7	4	"l6" and l3	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	ADJ	ON	2006/10/12 19:20
L8	533	(increas\$3 adj power) with (control signal\$1 or "TFCI")	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	ADJ .	ON	2006/10/12 19:21
L9		I7 and I8	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	ADJ	ON	2006/10/12 19:21

## **EAST Search History**

L10	4	18 and (12 or 13)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	ADJ	ON	2006/10/12 19:22
L11	4	110 and 11	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	ADJ	ON	2006/10/12 19:24
L12	7767	714/704 or 714/746 or 455/572 or 455/? or 370/441 370/?	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	ADJ	ON	2006/10/12 19:24
L13	1	l11 and l12	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	ADJ	ON	2006/10/12 19:24

10/12/06 7:38:38 PM C:\Documents and Settings\PChung\My Documents\EAST\Workspaces\10609492.wsp